




Innfestingsbeslag 12070.

B-mål Tilpasses temperaturbevegelser.
B=0 ved låsningspunkt.
Se Tegning P5050-810

